


If there are pots R3, R5 outside the board  
pots R32, R33 on the board should be turned max right.



PDE 41, PDE 41W, PDE 41LT