


VIKING™ HELMETS

General Cleaning Guidelines



Follow these steps

to help increase the longevity and usefulness of your VIKING™ helmet.

- Lightly blow off any loose dirt or debris from the helmet
- Use a soft microfiber cloth or eyewear-approved tissue to clean the Helmets and ADF lens
- Rinse your helmet & lens with cool water and wipe clean with lens-safe tissue
- Only use lens cleaning products to clean by spraying eyewear-specific cleaning solution directly onto the ADF lens and wipe clean with lens-safe tissue
- Store helmet in a secure spot like a locker, or shelving, but never on a table or around your work area.

General Guidelines

WARNING

Maintenance And Storage

- Read and follow all steps set forth in the VIKING™ Welding Helmet Operator's Manual.
- Replace damaged or dirty cover lenses. ADF lens can be affected by the state of the cover lenses.
- Never use solvents or abrasive cleaning solutions to clean the helmet. Keep water and other fluids the helmet. Keep water and other fluids out of the ADF lens.
- Cleaning is recommended after each use

Important Notice:

- Follow your facility's protocols for proper disposal of cleaning equipment and solutions.

Cleaning VIKING™ Welding Helmet.

1. Use a warm, mild detergent cleaning solution.
2. Wipe with a soft cloth until clean.
 - a. **DO NOT** use detergents that contain lanolin or other oils, organic or chlorinated solvents or abrasive cleaning agents.
3. Clean sensors and solar cells with soapy water solution and a clean cloth and wipe dry with a lint-free cloth. **DO NOT** submerge shade cartridge in water or other solution.

Rinsing VIKING™ Welding Helmet.

1. Rinse the VIKING™ Welding Helmet by wiping with a clean soft cloth, lightly dampened with clean warm water, and thoroughly dry before use or storage.

Disinfecting Safety Glasses & Goggles Lenses.

1. Disinfect the Safety Glasses & Goggles lens by wiping with a suitable disinfecting material recommended by the EPA after drying and before use: <https://www.epa.gov/pesticide-registration/selected-eparegistered-disinfectants>.

Important Notice:

- Ensure all components are dry prior to reuse or storage.
- The cleaned Helmet should be carefully inspected per the VIKING™ Welding Helmet Operator's Manual.
- Store Helmet when not in use in accordance with the Operator's Manual.

CUSTOMER ASSISTANCE POLICY

The Lincoln Electric Company is manufacturing and selling high quality welding equipment, consumables, and cutting equipment. Our challenge is to meet the needs of our customers and to exceed their expectations. On occasion, purchasers may ask Lincoln Electric for information or advice about their use of our products. Our employees respond to inquiries to the best of their ability based on information provided to them by the customers and the knowledge they may have concerning the application. Our employees, however, are not in a position to verify the information provided or to evaluate the engineering requirements for the particular weldment. Accordingly, Lincoln Electric does not warrant or guarantee or assume any liability with respect to such information or advice. Moreover, the provision of such information or advice does not create, expand, or alter any warranty on our products. Any express or implied warranty that might arise from the information or advice, including any implied warranty of merchantability or any warranty of fitness for any customers' particular purpose is specifically disclaimed.

Lincoln Electric is a responsive manufacturer, but the selection and use of specific products sold by Lincoln Electric is solely within the control of, and remains the sole responsibility of the customer. Many variables beyond the control of Lincoln Electric affect the results obtained in applying these types of fabrication methods and service requirements.

Subject to Change – This information is accurate to the best of our knowledge at the time of printing. Please refer to www.lincolnelectric.com for any updated information.

All trademarks and registered trademarks are the property of their respective owners.